

17 AFS  
1/18/02



United States Steel  
Clairton Works  
400 State Street  
Clairton, PA 15025-1855

AFS # 42-003-00032  
APC 1-11-02  
ATPA 1-00 Outage Report  
DTA 1-02 0102

January 2, 2002

Dr. Roger C. Westman  
Department of Air Quality  
Bureau of Air Pollution Control  
301 Thirty-Ninth Street  
Pittsburgh, PA 15201

U.S. Environmental Protection Agency  
Region III  
Air, Radiation & Toxics Division  
1650 Arch Street  
Philadelphia, PA 19103-2029  
ATTN: James W. Hagedorn (3AT23)

Assistant Council  
Department of Environmental Protection  
Southwest Region  
400 Waterfront Drive  
Pittsburgh, PA 15222-4745  
ATTN: Ward Kelsey, Esq.

Department of Justice  
Environmental and Natural Resource Division  
Environmental Enforcement Section  
P.O. Box 7611  
Ben Franklin Station  
Washington, D.C. 20044  
ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0001  
SCOT Plant  
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the planned outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

R. R. Terza  
General Manager  
Clairton Works Raw Materials

NOTICE OF PLANNED OUTAGE OF EQUIPMENT  
ARTICLE XXI - SECTION 2108.1

1. Planned Outage Number: 02-0001
2. Date & Time of Breakdown: Date: 01/08/02 Time: ~0800 hours
3. Company Name: USX Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: SCOT Plant
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The SCOT Plant will be taken out of service for approximately 2 days to switch reactors.
8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)  
Elevated H<sub>2</sub>S at the incinerator stack, causing increased SO<sub>2</sub> at point of combustion.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO<sub>2</sub> is an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted).  
Light to Moderate
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).  
The SCOT Plant will return to normal upon completion of the task.
10. Facility back in operation - Date: Time: hours

Signature Coleen M. Davis Date 1/2/02  
Coleen M. Davis  
Environmental Control Engineer Phone: 233-1015



United States Steel  
Clairton Works  
400 State Street  
Clairton, PA 15025-1855

January 9, 2002

Dr. Roger C. Westman  
Department of Air Quality  
Bureau of Air Pollution Control  
301 Thirty-Ninth Street  
Pittsburgh, PA 15201

U.S. Environmental Protection Agency  
Region III  
Air, Radiation & Toxics Division  
1650 Arch Street  
Philadelphia, PA 19103-2029  
ATTN: James W. Hagedorn (3AT23)

Assistant Council  
Department of Environmental Protection  
Southwest Region  
400 Waterfront Drive  
Pittsburgh, PA 15222-4745  
ATTN: Ward Kelsey, Esq.

Department of Justice  
Environmental and Natural Resource Division  
Environmental Enforcement Section  
P.O. Box 7611  
Ben Franklin Station  
Washington, D.C. 20044  
ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0005  
Sulfur Plant Incinerator Stack  
USS Clairton Works

Gentlemen:


The attached form confirms our verbal report of the planned outage. Any questions concerning this matter should be referred to Daniel J. Belack at 233-1114.

Sincerely,

R. R. Terza  
General Manager  
Clairton Works Raw Materials

NOTICE OF PLANNED OUTAGE OF EQUIPMENT  
ARTICLE XXI - SECTION 2108.1

1. Planned Outage Number: 02-0005
2. Date & Time of Breakdown: Specific date and time undetermined, but will occur between 01/10/02 and 01/15/02
3. Company Name: USX Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: Sulfur Plant Incinerator Stack
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The spare sulfur plant incinerator stack will be unavailable for service for approximately 7 days to clean the piping from the Claus Plant to the incinerator stack.
8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)  
The spare incinerator stack will carry the load. No environmental impact is expected.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO<sub>2</sub> is an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted).  
No environmental impact.
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).  
The spare incinerator and stack will carry the load.
10. Facility back in operation - Date: Time: hours

Signature  Date 1-10-02  
Daniel J. Belack  
Environmental Control Engineer Phone: 233-1114